



3.B.3 INDUSTRIAL (OPEN-TYPE INDUSTRIAL RADIOGRAPHY, NON-DESTRUCTIVE TESTING and APPLICATIONS UTILIZING LINAC and COMPUTED TOMOGRAPHY)

CHECKLIST OF REQUIREMENTS	WHERE TO SECURE
1. Proof of Business Name (SEC or DTI Registration or Mayor' Business Permit) (Initial & 1st Renewal Application in the FDA Portal)	Mayor's office from the municipality where the facility is located/ Department of Trade and Industry/ Securities and Exchange Commission
2. Proof of subscription to personal dose monitor (TLD or OSL) from authorized personal dosimetry service provider (Initial & 1st Renewal Application in the FDA Portal)	DTI-PAB Accredited Personal Dosimetry Service Providers
3. Certificate of training of the radiation protection officer (RPO) in an appropriate radiation protection training course conducted by an organization recognized by the CDRRHR (Initial & 1st Renewal Application in the FDA Portal)	Recognized training provider of FDA
4. Provision of radiation survey meter (Initial & 1st Renewal Application in the FDA Portal)	Supplier of Radiation Survey Meter Calibration Services providers
5. Valid Radiation Survey Meter Calibration Certificate (Initial & 1st Renewal Application in the FDA Portal)	
6. If transportable, valid vehicle LTO registration (OR/CR) (Initial & 1st Renewal Application in the FDA Portal)	Land Transportation Office
7. Brochure/Literature of the machine (Initial & 1st Renewal Application in the FDA Portal)	Machine Manufacturer/Supplier
8. Periodic workplace area monitoring results within the validity period of the expired license (For facilities with OSL exemption) (Renewal Only)	Radiation Protection Officer of the facility
9. Copy of the latest License to Operate (Renewal Only)	Applicant