ATC Healthcare International Corp. Recalls Multivitamins + Lysine + Iron Capsule [Vitalyfe] under Registration No.: DR-XY46210

[--No Other Products Affected--]

Contact:

ATC Healthcare International Corp. 0909-333-3333 / 0917-562-3333 Media Contact: atchealthcare.com.ph customercare@atchealthcare.com.ph

FOR IMMEDIATE RELEASE – January 10, 2024 – ATC Healthcare International Corp. is recalling Batch number **O0B02HA22** of Multivitamins + Lysine + Iron Capsule [Vitalyfe]. This recall was initiated due to a failed assay by FDA result for Pyridoxine HCl (Vit. B6), Riboflavin (Vit. B2), Thiamine Mononitrate (Vit. B1).

This action relates only to ATC Healthcare International Corp. products with any of these Batch number printed on the package:

· O0B02HA22

No other Batch number, or any other ATC Healthcare International Corp. products, are involved in this action.

Only these specific lot codes are impacted. Customers are asked to remove all products with batch number listed below out of distribution immediately. Customers may call the number listed or visit our website for instructions on what to do with the product.

PRODUCT	BACTCH	REGISTRATION	MANUFACTURING	EXPIRATION
	NUMBER	NUMBER	DATE	DATE
MULTIVITAMINS + LYSINE + IRON CAPSULE [VTALYFE]	O0B02LA22	DR-XY46210	15 AUGUST 2022	15 AUGUST 2024

ATC Healthcare International Corp. is conducting this recall because **Multivitamins + Lysine + Iron Capsule [Vitalyfe]** failed to meet the required specifications for Pyridoxine HCl (Vit. B6), Riboflavin (Vit. B2), Thiamine Mononitrate (Vit. B1). We have not received any reports of illness associated with this product, but we are recalling this product out of an abundance of caution.

For more information or assistance, please contact us at 0909-333-3333 / 0917-562-3333 (Monday to Friday, 9:30 a.m. to 5 p.m.) or via our website at **atchealthcare.com.ph**

